# Weathertzatton Assistance Program

## Work Order (Bid Form)

#### **WORK ORDER INFORMATION**

Work Order Name: WO/50005DE4037/1
Work Order Type: Weatherization
Audit Name: Audit (71)

#### **CLIENT INFORMATION**

Client Name: Address:

**Client ID:** 50005DE4037 , 38063

Alt. Client ID:

#### **AGENCY INFORMATION**

Agency: Delta Human Resource Agency Agency Phone: (901) 476-5226

**Address:** P. O. Box 634 **Fax:** (901) 476-5258

Company Name & License Number:	
Contractor's Signature:	

#### **COMMENT**

### Measures

Measure 1 R	epalce 38 x 36 broken par	ne in W2		Componen	ts			Inspected
Comment								
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	<b>Unit Cost</b>	Total	Qty	<b>Unit Cost</b>	Total
10 Unspecified	Misc Material	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
Measure 2 R	eplace 22 x 16 broken par	ne in W5		Componen				Inspected
		ne in W5	Qty	Componen  Estimated  Unit Cost		Qty	Actual Unit Cost	Inspected Total
Comment			<b>Qty</b> 1	Estimated		Qty	Actual	
Comment  # Material / Labor	Description / Comment	Units	_	Estimated		Qty	Actual	
Comment  # Material / Labor  10 Unspecified	Description / Comment	Units	_	Estimated		Qty	Actual	
Comment  # Material / Labor  10 Unspecified	Description / Comment	Units	_	Estimated		Qty	Actual	
Comment  # Material / Labor  10 Unspecified	Description / Comment	Units Each	1	Estimated			Actual	
# Material / Labor 10 Unspecified Other Detail	Description / Comment	Units Each	1	Estimated Unit Cost			Actual Unit Cost	
Comment  # Material / Labor  10 Unspecified	Description / Comment	Units Each	1	Estimated Unit Cost			Actual Unit Cost	
# Material / Labor 10 Unspecified Other Detail	Description / Comment	Units Each	1	Estimated Unit Cost			Actual Unit Cost	

	place 32 x 24 broken par	ne in W1		Componen	ts		•	nspecte
Comment				Estimated	,		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
0 Unspecified	Misc Material	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
	place 34 x 26 broken par	ne in W3		Componen	ts		1	Inspecte
	place 34 x 26 broken par	ne in W3		Componen Estimated			Actual	Inspecte
Comment	place 34 x 26 broken par  Description / Comment	ne in W3	Qty	•		Qty		nspecte
Comment # Material / Labor			<b>Qty</b> 1	Estimated		Qty	Actual	
Comment # Material / Labor	Description / Comment	Units	_	Estimated		Qty	Actual	
Comment  # Material / Labor  0 Unspecified	Description / Comment	Units	_	Estimated		Qty	Actual	
<ul><li>Comment</li><li># Material / Labor</li><li>0 Unspecified</li></ul>	Description / Comment	Units	_	Estimated		Qty	Actual	
# Material / Labor Unspecified	Description / Comment	Units Each	1	Estimated			Actual	

Measure 5 Infil	tration Redctn			Componen	ts		ı	nspecte
	noe and caulk Door 1 noe and caule Door 2							
			Estimated	1	Actual	I		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Miscellaneous     Supplies	Infiltration Reduction	Each	1					
Other Detail						1		
			Measur	e Sub Total:		,	Sub Total:	
Field Notes:								
Field Notes:								
Measure 6 DW	H Pipe Insulation			Componen	ts			Inspecte
Measure 6 DW	H Pipe Insulation			-				Inspecte
Measure 6 DW Comment	·	Unio		Estimated	1		Actual	
Measure 6 DW Comment # Material / Labor	Description / Comment	<b>Units</b>	Qty	-		Qty		Inspecte
Measure 6 DW Comment # Material / Labor	·	<i>Units</i> Each	<b>Qty</b> 1	Estimated	1	Qty	Actual	
Measure 6 DW Comment # Material / Labor 1 Insulation	Description / Comment		_	Estimated	1	Qty	Actual	
Measure 6 DW Comment  # Material / Labor 1 Insulation	Description / Comment  DHW Pipe Insulation	Each	1	Estimated	1	Qty	Actual	
Measure 6 DW Comment  # Material / Labor 1 Insulation 2 Labor	Description / Comment  DHW Pipe Insulation	Each	1	Estimated	1	Qty	Actual	
Measure 6 DW Comment  # Material / Labor 1 Insulation 2 Labor	Description / Comment  DHW Pipe Insulation	Each	1	Estimated	1	Qty	Actual	
Measure 6 DW Comment  # Material / Labor 1 Insulation 2 Labor	Description / Comment  DHW Pipe Insulation	Each Each	1 1	Estimated	1		Actual	

	Measure 7 DV	VH Tank Insulation			Componen	ts			Inspected
C	omment								
					Estimated	·		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Hot Water Equipment	DHW Tank Insulation	Each	1					
2	Labor	DHW Tank Insulation	Each	1					
C	Other Detail			,			,		
L									
							] []	0.1.7.4.1	
				Measure	e Sub Total:		•	Sub Total:	
	Measure 8 Wa	all Insulation			Componen				Inspected
		December / October 1	11-11-		Estimated	<del></del>		Actual	T- (-1
	Material / Labor Insulation	Description / Comment  Wall Insulation - Blown Cellulose - 2x4 Filled	<i>Units</i> SqFt	<b>Qty</b> 225.4	Unit Cost	Total	Qty	Unit Cost	Total
C	Other Detail								
L				Measure	e Sub Total:			Sub Total:	

Measure 9 Wa	II Insulation			Componen	<b>ts</b> 3		ı	Inspected
Comment								
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	140					
Other Detail								
			Measure	e Sub Total:		] .	Sub Total:	
Measure 10 Wa	II Insulation			Componen	te 1			Inspected
	ii iiisulatioii			Componen			•	
Comment				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	165.6					
Other Detail								
			Measure	e Sub Total:			Sub Total:	
Field Notes:								

Measure 11 Floor Ins. R-19				Componen	<i>t</i> s 1		1	Inspected
Comment								
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Floor Insulation - Fiberglass Batts - R-19	SqFt	916					
Other Detail								
			Measure	e Sub Total:			Sub Total:	
Field Notes:						•		
Measure 12 Sto	rm Windows			Componen	ts 2 4 3			Inspected
	iiii wiiidows			Componen	2,7,0		•	
Comment				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
	-		_	Offic Cost	TOtal	Qiy	Omit Cost	Total
1 Windows	Storm Window	SqFt	45.06					
2 Labor	Storm Window	SqFt	45.06					
0. Oth an	Ota was Windows	□ a a b	2					
3 Other	Storm Window	Each Window	3					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
			mouour	o oub rotui.				
Field Notes:								
rieid Notes.								
rieid Notes.								

1	Measure 13 CO Monitor is Needed				Componen	ts		ı	Inspected
C	omment								
					Estimated	<u> </u>		Actual	
#	Material / Labor	Description / Comment	Units	Qty	<b>Unit Cost</b>	Total	Qty	<b>Unit Cost</b>	Total
1	Health and Safety Items	CO monitor	Each	1					
2	Labor	Labor	Hour	1					
0	ther Detail								
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								
	Manager 14 Fix	Any Other Heating Syst	lom Drobl		Composo	40			Inspected
		Any Other Heating Syst							Inspected
C	omment Replace	unvented space heater	with vente	d heat	er <i>Estimated</i>	1	Otv	Actual	
<i>C</i> :	omment Replace	unvented space heater  Description / Comment	with vente	d heat	er		Qty		Inspected
<i>C</i> :	omment Replace	unvented space heater	with vente	d heat	er <i>Estimated</i>	1	Qty	Actual	
<b>C</b> (	omment Replace  Material / Labor  Health and Safety	unvented space heater  Description / Comment	with vente	d heat	er <i>Estimated</i>	1	Qty	Actual	
<b>C</b> (# 1 2	omment Replace Material / Labor Health and Safety Items Labor	unvented space heater  Description / Comment  Equipment	with vente <i>Units</i> Each	d heate Qty 1	er <i>Estimated</i>	1	Qty	Actual	
<b>C</b> (# 1 2	omment Replace Material / Labor Health and Safety Items	unvented space heater  Description / Comment  Equipment	with vente <i>Units</i> Each	d heate Qty 1	er <i>Estimated</i>	1	Qty	Actual	
<b>C</b> (# 1 2	omment Replace Material / Labor Health and Safety Items Labor	unvented space heater  Description / Comment  Equipment	with vente <i>Units</i> Each	d heate Qty 1	er <i>Estimated</i>	1	Qty	Actual	
<b>C</b> (# 1 2	omment Replace Material / Labor Health and Safety Items Labor	unvented space heater  Description / Comment  Equipment	with vente  Units Each  Hour	Qty 1	er <i>Estimated</i>	1		Actual	
# 1 2 <u>0</u>	Material / Labor Health and Safety Items Labor ther Detail	unvented space heater  Description / Comment  Equipment	with vente  Units Each  Hour	Qty 1	Estimated Unit Cost	1		Actual Unit Cost	
# 1 2 <u>0</u>	omment Replace Material / Labor Health and Safety Items Labor	unvented space heater  Description / Comment  Equipment	with vente  Units Each  Hour	Qty 1	Estimated Unit Cost	1		Actual Unit Cost	
# 1 2 <u>0</u>	Material / Labor Health and Safety Items Labor ther Detail	unvented space heater  Description / Comment  Equipment	with vente  Units Each  Hour	Qty 1	Estimated Unit Cost	1		Actual Unit Cost	

Measure 15 Fix Wiring Problems (Walls)				Componen	ts			Inspected
Comment Replace	2 receptacles in living ro	oom						
				Estimated	<u>'</u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	<b>Unit Cost</b>	Total	Qty	<b>Unit Cost</b>	Total
Health and Safety     Items	Equipment	Each	1					
2 Labor	Labor	Hour	1					
Other Detail						,		
						] []		
			Measur	e Sub Total:		}	Sub Total:	
Measure 16 Smo Comment	ke Detector is Needed			Componen	ts			Inspected
				Estimated	<u>'</u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safety Items	Smoke detector	Each	1					
2 Labor	Labor	Hour	1					
Other Detail								
						] []		
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
		Work O	rder Gra	nd Total:		Gran	d Total:	